



LARYEE Testing Machines

LOAD CALIBRATOR LYLC-100

USER'S INSTRUCTION MANUAL



Laryee Technology Co., Ltd



Add: No.248, Guanganmenwai Avenue, Xuanwu District, Beijing, China

Tel: +86-10-67086287 Fax: +86-10-67085997

Web: www.laryee.com

Email: info@laryee.com


I. Characters

- ◆ It suits for electrical-bridge type sensors such as load cell, torque sensor and pressure sensor, etc. With high accuracy and resolution, it can display the testing result;
- ◆ Each sensor can record 20 calibration points parameters, then up to different accuracy;
- ◆ Each calibrator can record 20 sensors calibration parameters at most.
- ◆ Unit of the measuring data can be changed: N, kN, MN, lbf, kgf, tf, etc.

II. Specification

- ◆ Accuracy: 0.3%, or 0.1% as special order
- ◆ Resolution: 0.001%
- ◆ Working power: 1 Phase, ~220V, 50HZ
- ◆ Related load cell: Bridge type load cell, and the output sensitivity is 1~4mV/V
- ◆ Dimension: 200mm×200mm×100mm Weight: 2KG

III. Control panel instruction







1. charging indicator: when charging, it is on; when finished, it is off
2. secondary screen: 2-bits, assists main screen, when in measuring state, it shows the channel number. When in holding status, it shows “H”
3. main screen: 7-bits, all main data and function code display.
4. different units indicate light
5. multi-function key

a. key function

SET: press it, enter the setting mode, choose the measuring channel, press again,

return to normal measuring mode.



 : press it, the showing value clear to zero. In the setting mode, shift the bit.

 : press it, the showing value will be hold, press it again, back to normal display.

In the setting mode, decrease the data

 : press it, enter the tare weight record state, and showing value clear to zero.

Press it again, back to normal display. In the setting mode, increase the data.

 : change the force measuring unit; in the setting mode, enter to check and save the calibration parameters.

b. display code definition

CHn: channel


C: mV/V value



F : calibration point





L : sensor full range value

H: hold state


IV. operation procedure




After turn on the power, press  key,, displays “-CHNxx-” and flash, press





 or  key to select a certain channel number, then:

- press  key——quit setting function, and enter measuring state.
- Press  key——enter channel to check and change parameter. The detail information see chapter V
- Press  key—— change the unit light to “mV/V”, then press  key to enter calibrating state. The detail information see chapter VI

V. check and change sensor parameter

1. in measuring state, press , displays “-CHn01-”, means select a channel, press

 or  key to choose a channel, press  then;



2. displays L=xx.xxx, means changing the sensor capacity of this channel, press , displays xx.xxxxx, meanwhile one bit flashing, press ,  and  to change the value, press  to confirm;
3. displays L=xx.xxx, meanwhile one unit indicate light is on, means changing the unit of the sensor, press , one unit indicate light flashing, press  and  to change, press  to confirm;
4. displays F1=xx.xx, means the first calibration point value of the sensor, press , press ,  and  to change the value, press  to confirm.
5. displays C1=xx.xx, means the mV/V(mA) value of the first calibration point of the sensor, press , press ,  and  to change the value, press  to confirm.
6. displays in turn F2=xx.xx, C2=xx.xx.....until Fn=xx.xx,Cn=xx.xx, change the value according to the calibration result strictly, after finishing changing each data, press  to confirm.
7. each sensor can restore 20 groups calibration data at most, if this sensor only written 5 group calibration data, then in next time checking, only displays 5 group calibration data and one group all zero data (all zero data is for inputting a new group of calibration data.
8. after finishing changing all the calibration data, press  to return up-grade menu, keep pressing  until return the measuring state, at this time, the measuring data displays according to the newly input calibration data.

Key attention: the input format of each sensor capacity will affect the measuring speed and accuracy, for example, the sensor capacity is 1000KN


































Input Format L=	Measuring speed	Measuring accuracy
1000.000	slow	high
01000.00	medium	medium
001000.0	fast	low

VI. Calibration of the sensor

For example, calibrating a 300KN sensor, 30kN, 60kN, 120kN, 1800kN, 240kN, 300kN are the calibrating points, and the calibration data store in the channel which you choose.

1. after turning on the power, press , change the indicate light to mV/V;
2. do not load on sensor, if necessary, press , clear the value to zero.
3. load on the sensor to 30kN, when the indicate value have not change, record the showing mV/V value.
4. by the same way, loading in turn to 60kN, 120kN, 180kN, 240kN and 300kN, record each corresponding showing data, as following format:

Num.	mV/V value (C)	Calibrating point (F)
1	F1=300.0000	C1=1.971200
2	F2=240.0000	C2=1.576100
3	F3=180.0000	C3=1.181500
4	F4=120.0000	C4=0.787350
5	F5=60.00000	C5=0.393390
6	F6=30.00000	C6=0.196600
7	F7=0.000000	C7=0.000000

5. begin to input data, press , choose the channel which you want to write in, for example “-CHNxx-”, press , showing L=0.0000, press , showing 0.000000, in the same time 1 bit flashing, press ,  and  to change to 300.00, press  to confirm;
6. showing L=300.0, the same time one unit indicate light lighting, press , unit light flashing, pressing  and  to change to KN position, press  to confirm.
7. showing F1=0.0000, press , showing 0.000000, one bit flashing, press ,  and  to change to 30.0000, press  to confirm.
8. showing C1=0.0000, press , showing 0.000000, and one bit flashing, press ,  and  to change to 0.196600, press  to confirm.
9. showing F2=0.0000, press , showing 0.000000, and one bit flashing, press ,  and  to change to 60.0000, press  to confirm.
10. showing C2=0.0000, press , showing 0.000000, and one bit flashing, press ,  and  to change to 0.393390, press  to confirm.
11. the same way in turn, F3 input 120.0000, C3 input 0.787350; F4 input 180.0000, C4 input 1.181500; F5 input 240.0000, C5 input 1.576100; F6 input 300.000, C6 input 1.971200.
12. finishing input, press , showing “-CHNxx-”, press  to save result and quit setting, entering measuring state.

REMARKS:

- 1. Load cell's Calibration Point parameter please refer to the Appendix(1).**
- 2. This load calibrator is equipped with 5 load cell, and verified by the national metrology center, the detail verification certificate is attached.**

Appendix(1):

Load cell's Calibration Point parameter

L=100.00

Calibration Point(KN)	calibration parameter (mv/V)
F1=100.0000	C1=1.966180
F2=50.0000	C2=0.982290

Attention:

- 1. Write these parameters in an idle channel of your Load Indicator.**
- 2. If the indicating value on load indicator is negative value, then please exchange the aviation plug of No.1 and No.5.**