

FHT 60 and FHT 100 Humidity and Temperature Meter



FHT 60



FHT 100

TECHNICAL DATA	FHT 60	FHT 100	FEATURES	SUPPLIED WITH FHT 60 & FHT 100
ART.-NO.	800100	800110		
Temperature range	-20 °C to +60 °C	-30 °C to +100 °C	<ul style="list-style-type: none"> Fast measurement of relative humidity and temperature 	<ul style="list-style-type: none"> Case Battery
Humidity range	0 % – 100 % RH	0 % – 100 % RH		
Fast response time	yes	yes	FHT 100 <ul style="list-style-type: none"> Dewpoint temperature measurement for recognition of mold building up and wet bulb temperature measurement (evaporation temperature) 	
Illuminated display	yes	yes		
Max HOLD	yes	yes		
Data HOLD	yes	yes		
Dewpoint temperature	no	-30 °C to +100 °C		
Wet bulb temperature	no	0 °C to +80 °C		
Accuracies:				
Humidity	± 3.5 % RH	± 2 % RH		
Temperature	± 2 °C	± 0.5 °C		
Dewpoint	–	± 0.5 °C		
Wet bulb	–	± 0.5 °C		