
## LINEAR GAGES AND DISPLAY UNIT LINEAR GAGE **IP65** Unit: mm BACK alarm WATERPROOF (out of tolerance) output outside 18.8 control control red light (out of upper limit) green light (within tolerance) red light (out of lower limit) to linear display unit gage output 7106-1 linear gage set zero set tolerance

- Linear gage: shock-proof, water proof, dust proof, suitable for high speed movement, long working life
- Display unit: set tolerance and make judgment (out of upper limit, within tolerance, out of lower limit), output the judgment to control outside devices, set zero and hold reading from outside





## LINEAR GAGE SPECIFICATION

Code	7106-11	7106-12
Measuring range	12mm	12mm
Resolution	0.01mm	0.001mm
Accuracy	20µm	5µm
Hysteresis	10µm	2µm
Measuring principle	capacity system	
Voltage	5V	
Sampling frequency	100 times/sec.	
Working life	ten million times	
Dust/waterproof	IP65	
Measuring force	1.5N	
Cable length	2m	
Data output	four-core wire	

## **DISPLAY UNIT SPECIFICATION**

Code	7106-1
Display	6 digits
Quantity of linear gages to be connected	1pc
Tolerance	set tolerance and make judgment with alarm and lights (out of upper limit, within tolerance, out of lower limit)
Output control	output the tolerance judgment (out of upper tolerance, within tolerance, out of lower tolerance) to control outside devices
Outside control	control the display units from outside (set zero, hold reading)
Data output	connect to PC
Power supply	DC 9~24V